Before

After. New heavy duty aluminum counter flashing installed on all HVAC units.

8/14/2009 8:34am

8/14/2009 8:52am


This was taking in water. It was trapped between the old and new roofs.

This wall is taking in water. The leaks are not our responsibility.